

Free Motor Check Inspection Report

Inspection ID: 12481 • Inspected On: Jun 18, 2026 • Inspected By: IM Inspector

Motorcycle Information

Brand:

Aprilia

Mileage:

100 km

Model:

Dorsoduro 750 ABS

Color:

Black White

Year:

2024

Number Plate:

HAFIZ TECH 4 TEST

Inspection Summary

20

Total Items

20

Passed

0

Issues

Inspection Items

No.	Inspection Point	Status	Comment	Image
1	Tire › Front › Condition, Expiration, Air Pressure	Pass	—	—
2	Wiring › Condition, Routing	Pass	—	—
3	Chain or Belt › Tension, Lubrication, Sprockets	Pass	—	—
4	Levels › Hydraulic Fluid Leaks › Leaks	Pass	—	—
5	Levels › Coolant Leaks › Leaks	Pass	—	—
6	Engine › Noise, Leaks and Condition	Pass	—	—
7	Gearbox › Noise & Clutch	Pass	—	—
8	Gearbox › Operations & Leaks	Pass	—	—
9	Suspension › Front › Left, Right	Pass	—	—
10	Suspension › Rear › Left, Right	Pass	—	—
11	Body Alignment	Pass	—	—
12	Tire › Rear › Condition, Expiration, Air Pressure	Pass	—	—
13	Coverset	Pass	—	—
14	Brakes › Front › Function, Operation, Pads, Rotors, Calipers	Pass	—	—

No.	Inspection Point	Status	Comment	Image
15	Brakes › Rear › Function, Operation, Pads, Rotors, Calipers	Pass	—	—
16	Headlamp › High & Low Beam › Condition, Operation, Aim	Pass	—	—
17	Tail Lamp › Condition, Operation, Aim	Pass	—	—
18	Turn Signals › Front & Rear, Left & Right	Pass	—	—
19	Switches › High & Low Beam	Pass	—	—
20	Switches › Turn Signals › Left, Right	Pass	—	—