


ITEM	PHOTO	ASSESSMENT TYPES
hdud.		Crack: ☐ FC1 ☒ FC2 ☐ FC3 ☐ FC4 ☒ WC1 ☐ WC2 ☐ WC3 ☐ WC4 Bent: ☐ B1 ☐ B2 ☒ B3 ☐ B4 Damage: ☐ D1 ☒ D2 ☒ D3 ☐ D4
Location: gdydy	Inspector's comments: 1. No defect observed. Area is in satisfactory condition. Inspector: adam (adam)	Impact Category: Minor: ☒ Moderate: ☐ Major: ☐
hfhdj.		Crack: ☐ FC1 ☐ FC2 ☒ FC3 ☐ FC4 ☐ WC1 ☒ WC2 ☐ WC3 ☐ WC4 Bent: ☐ B1 ☐ B2 ☐ B3 ☒ B4 Damage: ☐ D1 ☒ D2 ☐ D3 ☐ D4
Location: udhdjf	Inspector's comments: 1. Spalling of concrete cover exposing reinforcement bars. Inspector: adam (adam)	Impact Category: Minor: ☐ Moderate: ☒ Major: ☐

ITEM	PHOTO	
jdjd.		
Location: jdjd	Inspector's comments: 1. Fine crack noticed at road curb / pedestrian walkway. Slab reasonably level. Inspector: adam (adam)	