ACCRETECH

TOSEI (THAILAND) CO.,LTD.

AMATA CITY CHONBURI INDUSTRIAL ESTATE
700/633 Moo 7, Tambon Don Hua Roh
Amphur Muang Chonburi 20000
TEL: (66)38-193-282-3 FAX: (66)38-193-284
TAX ID. NO. 0115547000743

Issue	Checked	Approved
27 Feb 25 Uthen TSET	27 Feb 25 Siriwan TSET	27 Feb 25 Somsak Manager

Quotation Valid Until : 24-Jun-2025
Type : 15

QUOTATION
(Local Condition)

CUSTOMER NAME	NMB-MINEBEA THAI LTD. (LOCAL)	DATE	27 February 2025
ATTN. NAME	K.KUNLADA	QUOTATION NO.	6015544
ADDRESS	1 MOO 7, PHAHOLYOTHIN ROAD., K.M. 51 TAMBON CHIANG RAK NOI, AMPHOE BANGPA-IN AYUTTAYA PROVINCE THAILAND 13180	DATE OF DELIVERY	45 days after received P/O
CUSTOMER CODE	A85519		
FAX. NO.		TERM OF PAYMENT	30 Days From Invoice
PLACE OF DELIVERY	PMA		

ITEM	PRODUCT NO	DESCRIPTIONS NAME	SPEC	Q'ty	UNIT PRICE (BAHT)	AMOUNT (BAHT)
		Inspection & Repair		1(SET)		23,000.00
		Model : E-TS-1151B-P6, S/N : 515227				
		INCLUDED				
1	5RS-127	Repair fee Sigma		1		
2	5RS-012	Supplies assy Set Sigma E-TS-115X-OD		1		
3	0065702T	LVDT ASSY		1		
	Remark:	1) This quotation is for NMB-MINEBEA THAI LTD. (LOCAL)				
		2) Exchange Rate : 100 JPY = 23.9700 THB (Information from NMB for 02/2025)				
		3) Sale Contact :K.Noothchanat Mobile:081-869-8290 Email :Noothchanat@tosei.co.th				
		4) In case of quotation expires after 24-Jun-2025 We will return the repair unit back to the customer.				
		Please send your purchase order by email and send to mail : **po.tset@tosei.co.th**				
		Please remark quotation number or attach quotation sheet in PO order all time for protect mistake order.				

ACCRETECH TSE TOSEI (THAILAND) CO.,LTD.

Twenty Four Thousand Six Hundred Ten Baht Only		TOTAL	23,000.00
		ADDED TAX 7%	1,610.00
		GRAND TOTAL	24,610.00

Customer Confirm Ordering

		Name : .....
		Position : .....
		Tel : .....
		Date : .....
Stamp	Signature	

Important notice

The product (s) as quoted above may be imposed an embargo on the exportation from Japan even before or after signing a contract when the MET (Ministry of Economy, Trade and Industry) judges that the goods come under Security, Export Control Law of Japanese Government. You are requested to notify to TOSEI (THAILAND) CO., LTD. In advance by written before you transfer or resell the product(s) to other parties.

Document No. :	
Revision :	
Effective Date :	

TOSEI (THAILAND) CO.,LTD.
AMATA CITY CHONBURI INDUSTRIAL ESTATE
700/633 Moo 7, Tambon Don Hua Roh,
Amphur NMB-MINEBEA THAI LIMITED (LOCAL) / NMB-PMA
TEL: (66)38-193-282-3 FAX: (66)38-193-284

Repair Report Sheet

Model Name :	E-TS-1151B	Serial No. : 515227	Request Date : 24/2/2568	Report Date : 26/2/2568
Customer Name :	NMB-MINEBEA THAI LIMITED (LOCAL) / NMB-PMA	Customer in charge :	Checked Date : 26/2/2568	Quotation No. : 6015544
Agency Name :	TOSEI (THAILAND) CO., LTD.	Tosei in charge : K. Nootchanat	Repaired Date :	Specsheet No. :

Item	Check item	Specification	Judgment Before Repairs 26/2/2568		Judgment After Repairs		NG Parts	
1	**Overview**						Image 01	Image 02
	1) Body	*OK/NG*	OK					
	2) Cable Assy	*OK/NG*	OK					
	3) Air Retact / Electric Retract	*OK/NG*	-					
2	**Measuring**		G1	G2	G1	G2		
	2.1) Signal		OK	OK				
	2.2) Measuring Force (N.)		0.3	0.4				
	2.3) Front Travel (mm.)		-0.36	-0.37				
	2.4) Repeatability (μm/25 time)		4.6	2.4			Image 03	Image 04
	2.5) Linearity (μm.)		2.2	2.4				
	2.6) Retract (mm.)		-	-				
3	**Inside**							
	3.1) Insulation Cable Ass'y	*OK/NG*	OK					
	3.2) Insulation Bobbin Ass'y	*OK/NG*	NG					
	3.3) Lever	*OK/NG*	OK					
	3.4) Core assy	*OK/NG*	OK					
	3.5) Board	*OK/NG*	OK					

4 Investigation and Repairing Comment

Judgement Repair

4.1) First investigation result

- We found that the insulation gauge is below normal.
- We found that the measuring force is below normal.
- We found that the front travel more than normal.
- We found that the repeatability more than normal.
- We found that the linearity more than normal.

NG

4.2) Checking inside gage

- We found that the insulation bobbin assy is below normal.
- We found that the leaf spring is bend.

บริษัท โทเซอิ (ประเทศไทย) จำกัด ACCRETECH TSE TOSEI (THAILAND) CO.,LTD.

4.3) After repair status.

Repairman in charge

Uthen

5 3 Months Warranty

Start Warranty	
Expired Warranty	

Warranty Condition

1) Warranty for products damaged or unusable, by repairs under normal usage conditions. And 3 months warranty, start from customer receive product.

2) In the event that the product is found to be damaged or unusable as a result of repairs, the company will change the equipment and repair the product and return it within 14 days from the date of receiving the product and notifying the claim.