INFACT TECHNOLOGY SYSTEM CO.,LTD.
45 Soi Phaholyothin 63 Phaholyothin Road Anusawaree
Bangkhen Bangkok 10220 Tel : 02 9723270 Fax : 02 9723274
E-mail : contact@infact.co.th Web : www.infact.co.th

Quotation No. S250306

Date: March 31, 2025

To:
Minebea Thai Co., Ltd.
1 Moo.7, Phaholyothin Rd.,Km.51, Chiang Rak-Noi,Bang Pa-in, Ayutthaya 13180
Tel: 1856

Attn: **K.Kunlada**

CC:

Dear Sir,

In response to your valued enquiry, We have the pleasure in offering for your consideration our following quotation.

Item	Part No.	Description	Q'ty	Unit Price Baht	Total Amount Baht
		Service Charge For Check			
1		**Machine Smart Scope OGP Profile CCPCC-20** **Serial Number : QL2002020**	**1**	**4,000.00**	**4,000.00**
		Date: 28 March 2025			

Sub Total (Baht)	**4,000.00**
Total (Baht)	**4,000.00**
Vat 7%	**280.00**
Grand Total (Baht)	**4,280.00**

Payment 30 Days
Delivery 4 Weeks after due date and receive p/o
Please send PO to Email : admin2@infact.co.th / admin@infact.co.th

We shall very much honored by your entrusting with your valued order Wishing to assure you our prompt service in its execution.

Sincerely Yours

Athitaya	Thongchai
Prepared By	**Approved By**

infact Technology System Co., Ltd.
บริษัท อินแฟคท์ เทคโนโลยี ซีสเต็ม จำกัด
INFACT TECHNOLOGY SYSTEM CO.,LTD.

45 ซอยพหลโยธิน 63 ถนนพหลโยธิน แขวงอนุสาวรีย์ เขตบางเขน กรุงเทพมหานคร 10220
45 Soi Phaholyothin 63, Phaholyothin Road, Anusawaree, Bangkhen, Bangkok 10220
TEL : 0-2972-3270 FAX : 0-2972-3274 E-mail Address : inf@infacttechnology.com www. infacttechnology.com

SR -

Date : 28 / 3 / 68

Service Report / Invoice

Customer Name : Minebea (บางปะอิน)
Address :
Contact Person : K. พิศชัยชา Phone No. 0968595832 Ext.

Machine and Software Detail

Machine Type : PROFile CCP CC-20 Serial Number : QL2002020
Temparature : 25°C Humidity : 49%

Job Detail

☐ Calibration ☑ Maintenance ☐ Repair or Replace part

3D Non-Contact Measuring Machine

Windows O/S
Software
Version

☐ New installation machine		
☐ Movement machine		
☐ Clean and Lubricate machine		
☐ Alignment Camera set		
☐ Optic Calibration	☐ Pass	☐ Fall
☐ Non-linear XY Calibration	☐ Pass	☐ Fall
☐ Linear Z Calibration	☐ Pass	☐ Fall
☐ Laser Calibration	☐ Pass	☐ Fall
☐ Touch Probe Calibration	☐ Pass	☐ Fall
☐ Other :		

Load Tester

☐ Compression/Tension ☐ Torsion Spring
Capacity N

☐ Load Calibration	☐ Pass	☐ Fall
☐ Displacement Calibration	☐ Pass	☐ Fall
☐ Clean and Lubricate		
☐ Other		

Machine problem

- ภาพหน้าจอไม่ชัดเจน ไม่สามารถทำการวัดงานได้
เกิดจากมีคราบน้ำมัน อยู่บริเวณ กระจกสะท้อน
ภายในเครื่อง และหน้า Lens.

Action

- ทำความสะอาดบริเวณกระจกสะท้อนภายใน ด้วย
[illegible]ทำความ สะอาดคราบน้ำมันเช็ดให้สะอาด รอบตัว Lens.

Judgement ☑ Job done ☐ Claim warranty ☐ Buy new part

Comment or Remark

- เริ่มงาน 10:00 → 11:30 น.

Service Charge Amount Baht

อรวิน สีรุ่งแสง
( )
(28 / Mar / 25)
Authorized Signature

Patara
(28 / 3 / 68)
Incharge By