



REPAIR ORDER
COST PROOF

Date : Jun 26, 2024
Unit Owner: 905 Truck and Trailer Repair
Invoice To: 905 Truck and Trailer Repair

Location : 905 Truck and Trailer
RO # : WO002487
Page : 1 /1

Unit	U225	VIN	12365497
Description	Test		
Make	ALLOY	Model	DUAL AXLE
		Year	2024
License		Tire Size	
		Engine	

Activity Description								
Task	SYS	ASM	Description/Notes	Reason	Actual	Hr Cost	Cost	Sublet
24	050	000	Accessories Group	1	0.00	0.00	0.00	0.00
Part No.		Description			Actual Part	Unit Cost	Cost	Sublet
123		GREASE			1 EA	12.00	12.00	0.00
BOLT1		Bolt One			1 EA	25.00	25.00	0.00
0220		Test			1 EA	50.00	50.00	0.00
1229300		EXHAUST PIPE			1 EA	113.00	113.00	0.00
ACME-J18		J-18 REQ EQ			-1 EA	50.00	-50.00	0.00
Parts Subtotal							150.00	0.00

LABOUR COST	0.00	SUBLET	0.00
PARTS COST	150.00	SUBLET	0.00
REPAIR ORDER TOTAL			150.00