Company Name

438/A, 2nd Floor, Kamarajar Road
Peelamedu, Chitra Nagar,
Lakshmipuram, Coimbatore - 641004
Phone: +91 22 1234 5678

SLIVER PRODUCTION REPORT

Date	2026-04-27
Machine Number	M1
Material Name	50s_radha_orange
Yarn	cotton
Color	orange
Counts	002
Threshold	5
Total Inspected	1339
Good	1313
Defective	26
Start Time	2026-04-27 12:24:01
End Time	2026-04-27 13:00:57

TOTAL SLIVER BREAKDOWN

Category	Count
Total Inspected	**1339**
Good	1313
Defective	26

DEFECTS LOG

ID	Defect Time	Job ID	Image	Defect Type
1	2026-04-27 13:00:27	50s_radha_orange		defect | Strip: 3
2	2026-04-27 13:00:18	50s_radha_orange		defect | Strip: 4,5
3	2026-04-27 12:59:50	50s_radha_orange		defect | Strip: 5
4	2026-04-27 12:59:41	50s_radha_orange		defect | Strip: 3
5	2026-04-27 12:59:18	50s_radha_orange		defect | Strip: 5