Company Name

438/A, 2nd Floor, Kamarajar Road
Peelamedu, Chitra Nagar,
Lakshmipuram, Coimbatore - 641004
Phone: +91 22 1234 5678

SLIVER PRODUCTION REPORT

Date	2026-04-25
Machine Number	M1
Material Name	002_cotton_orange
Yarn	cotton
Color	orange
Counts	002
Threshold	5
Total Inspected	6
Good	0
Defective	6
Start Time	2026-04-25 15:47:05
End Time	2026-04-25 15:47:10

TOTAL SLIVER BREAKDOWN

Category	Count
Total Inspected	**6**
Good	0
Defective	6

DEFECTS LOG

ID	Defect Time	Job ID	Image	Defect Type
1	2026-04-25 15:47:10	002_cotton_orange		strip missing | Strip: missing
2	2026-04-25 15:47:09	002_cotton_orange		defect | Strip: 1,2,3,4,5,6,7,8
3	2026-04-25 15:47:08	002_cotton_orange		strip missing | Strip: missing
4	2026-04-25 15:47:07	002_cotton_orange		strip missing | Strip: missing
5	2026-04-25 15:47:06	002_cotton_orange		strip missing | Strip: missing