Company Name

438/A, 2nd Floor, Kamarajar Road
Peelamedu, Chitra Nagar,
Lakshmipuram, Coimbatore - 641004
Phone: +91 22 1234 5678

SLIVER PRODUCTION REPORT

Date	2026-04-27
Machine Number	M1
Material Name	001_COTTON_TRIAL
Yarn	COTTON
Color	TRIAL
Counts	002
Threshold	1
Total Inspected	26
Good	11
Defective	15
Start Time	2026-04-27 10:40:10
End Time	2026-04-27 14:30:53

TOTAL SLIVER BREAKDOWN

Category	Count
Total Inspected	**26**
Good	11
Defective	15

DEFECTS LOG

ID	Defect Time	Job ID	Image	Defect Type
1	2026-04-27 14:30:53	001_COTTON_TRIAL		defect | Strip: 1,2,7
2	2026-04-27 14:30:33	001_COTTON_TRIAL		defect | Strip: 1,2,7
3	2026-04-27 13:09:56	001_COTTON_TRIAL		defect
4	2026-04-27 12:39:54	001_COTTON_TRIAL		defect
5	2026-04-27 12:31:25	001_COTTON_TRIAL		defect
6	2026-04-27 12:31:20	001_COTTON_TRIAL		defect
7	2026-04-27 12:29:10	001_COTTON_TRIAL		defect
8	2026-04-27 10:40:17	001_COTTON_TRIAL		strip missing | Strip: missing
9	2026-04-27 10:40:16	001_COTTON_TRIAL		strip missing | Strip: missing
10	2026-04-27 10:40:15	001_COTTON_TRIAL		strip missing | Strip: missing
11	2026-04-27 10:40:14	001_COTTON_TRIAL		strip missing | Strip: missing
12	2026-04-27 10:40:13	001_COTTON_TRIAL		strip missing | Strip: missing

ID	Defect Time	Job ID	Image	Defect Type
13	2026-04-27 10:40:12	001_COTTON_TRIAL		strip missing | Strip: missing
14	2026-04-27 10:40:11	001_COTTON_TRIAL		strip missing | Strip: missing
15	2026-04-27 10:40:10	001_COTTON_TRIAL		strip missing | Strip: missing