

Vehicle Inspection Report
Certificate No.: 5g2rzw0isw



345678 RTO	TS07UH04 Registration No
01-08-2018 Reg. Date	Petrol Fuel Type
Black Color	N/A Body Type
Manual Transmission	2 No. of Owner

Commercial

Ford Ecosport 2015-2021 1.5 TDCi Trend
BSIV



Banglore Urban, Karnataka

6.37 Lakh

Vehical Details			
JPXXXXX Engine Number	NA Insurance Validity date	Yes Is the car under Hypothecation	876756 Chassis Number
Not Available Type of Insurance	No RC Available	yes bank ltd If YesName of financier	NA Customer Number
John doe Client Name			


Body Frame






A pillar left	Good	A Pillar Right	Average	B Pillar Left	Broken
B Pillar Right	Good	C Pillar Left	N/A	C Pillar Right	Bad
Front Pannel	Good	Quarter Pannel Left	N/A	Quarter Panel Right	Bad
Running Board Left	Good	Roof Quality	Average	Dickey Floor	Broken
Quarter Pannel Robotic Punches Original	Bad	Running Board Punches	N/A	Running Board Left	Good


Exterior Details



Bumper Front	Good	Head Lamps RHS	Average	Fender Right	Broken
Bumper Rear	Good	Tail Lamp	N/A	Fender Left	Bad
Front Windscreen	Good	Paint Original	N/A	Fender Left	Bad
Bonnet	Scarteled	Dickey	Average	Front Door RHS	Broken
Front Door Glass RHS	Bad	Rear Door RHS	N/A	Rear Door LHS	Good
Bonnet	Bad	ORVM Right	N/A	ORVM Left	Good
Front Door Glass RHS	Bad	Front Door Glass LHS	N/A	Rear Door Glass RHS	Good
Rear Door Glass LHS	Bad				


Engine Transmission






Engine Oil Level	Good	Engine Oil Quality	Average	Engine Coolant Level	Broken
Engine Coolant Quality	Good	Radiator	N/A	Exhust Emission	Bad
Gear Box Sound	Good	Gear Shifting Mode	N/A	Acceleration Pickup	Bad

Electrical




Combination Switch	Good	Wiper	Average	Engine Oil Light	Broken
Engine Coolant Temp Light	Good	Indicator Lights	N/A		

Tyres



Front Tyre RHS	1111	Front Tyre LHS	1212	Rear Tyre RHS	1111
Rear Tyre LHSRear Tyre LHS	1111	Spare TyreSpare Tyre	1212		

Other



Front Tyre RHS	11	Front Tyre LHS	12	Rear Tyre RHS	11
Gear Box	11				

Estimated Assessment

Buyer Margin	1100	Warranty Cost	1200	Refurb Cost	1100
Trasportation Cost	N/A	Insurance Cost	N/A	Parking Charges	N/A
RTOExpenses	N/A	Taxes	N/A	Total Cost	N/A
RTOExpenses	N/A	Taxes	N/A	Total Cost	N/A

Vehicle Condition and Document Details



Vehile Condition	Breakdown	Parking Location	Yard	Insurance Type	11
RCStatus	N/A	Repo Date	19/02/2022		

Approved by

Vishwa V
License No: 83719
www.atebids.com