

DETAILED ACCIDENT REPORT (DAR)
ANNEXURE 'A'
MECHANICAL INSPECTION REPORT
(Submit Separate Mechanical Report for each vehicle)

H.T.V./M.G.V./L.G.V/FETAL		
1	Case FIR No.	413/2018
2	Under Section	304A
3	Police Station	Baramati
4	Registration No. of vehicle	MH12BG3483
5	Make, Name, Chassis No., RLW	Hero,Splender 123456789ASDF12 500kg
6	In case of HTV/MGV/LGV (a) Whether (LUPD) & (RUPD) installed? (For vehicle weighting 3.5 ton or more) (b) Whether speed governor installed & functional or otherwise?	Not Applicable, Not Applicable Not Applicable
7	In case of commercial vehicle: (a) Particulars of fitness (b) Particulars of permit	19-07-2017 27-07-2017
8	Point of impact and damage -	Point of Impact
9	Mechanical condition of the vehicle -	mechanically fit
10	Paint marks (if any)-	Not Available
11	Condition of the breaking System i.e. working or not?	Working
12	Whether the vehicle fitted with Anti-lock Breakng System (ABS)? a) If Yes, whether it is functioning or not? b) Whether trials regarding skid marks of ABS fitted vehicle have been carried out to estimate the speed of the vehicle	No Not Applicable No
13	Whether vehicle modified by: a) Installing CNG/LPG Kit b) Change of vehicle body	Not Installed No
14	Conditions of tyres-Whether original or retreated?	Original
15	Whether horn was installed and functinal?	Installed and Functioning

16	Whether the break lights and other functional?	Installed and Functioning
17	Conditions of safety bags in the vehicle	Not Applicable
18	Whether the vehicle properly maintained?	Yes
19	Whether the vehicle had faulty number plate?	No fitted
20	Whether the vehicle had tinted glass?	No
21	If the vehicle was educational institutional bus, Whether the vehicle fitted with the doors that can be shut and whether the vehicle has a suitable inscription to indicate that they are in the duty of an educational institute, as per the guidelines laid down in MC Mehta v. Union of India, (1998) I SCC 676 and MC Mehta v. Union of India, (1999) I SCC 413?	Not Available
22	Details of damage on vehicle	Damages new filling
23	a) Date of Inspection b) Place of Inspection	26-07-2017 Baramati
24	Motor vehicles in the accident	MH12BG3483

SANDEEP V MURKUTE

Inspector of Motor Vehicle
Baramati

Outward No.:

Date:

SHO
(Name & Stamp)