

**Service Report****S/No: CB00028**

Company Name: company1

Site Address: sqdqdqs

Lift No: 7665

**Caller's Description**☒ Breakdown☐ Travel Noise☐ Man Trap☐ Not Levelling☐ Light / Fan☒ Button / Indicator

Others:

**Type of Fault**☐ FALSE Call☐ Power Failure☐ Misuse☐ Water Ingress☐ Equipment Failure☐ Vandalism

Others:

**Fault Details**☐ Hydraulic Drive☐ ARD/EBOPS☐ Hydraulic System☐ Controller☐ Hoist Machine☐ Car Station / Circuit☐ Landing Door / Car Door☐ Car Cage / Counterweight☐ Landing Station Circuit☐ GOVERNOR / Safety Gear☐ Light / Fan Fitting☐ Off-Seal Leaking☐ Cartop / Shaft Electrical☐ Security System☐ Cartop / Shaft Mechanical☐ Supervisory / Lobby Vision

Others:

**Action Taken**☐ Repaired / Serviced☐ Shutdown☐ Replaced Parts☐ To Monitor / Follow Up☐ Quotation Required

Others:

**Description of Work Done**☐ Completed☒ Outstanding☐ Others

sqdqd

Client's Feedback (If any)

Serviceman Name / Sign

Client Name / Sign

On Site Date:

Handover Date:

Date:

Take Over Time:

Time Out: