
INSTALLATION SHEET Project Name: V80 90 DL SS BN CLR AGI3 10/4/2023




Customer: DAVID-06 Location: 2415 TEXAS


Quantity: 1

Project #: 10074021-I-MB


OUT OF PLUMB / LEVEL CONDITIONS



GLASS SIZES AND CLEARANCES



JUNCTIONS



Exterior

INSTALLATION COMMENTS

HARDWARE:

(2) V HINGES

INSTALLATION SHEET	Project Name: V80 90 DL SS BN CLR AGI3	10/4/2023
(1) V HANDLE (4) V CLIPS		
PLASTICS: (1) STRIKER (1) HINGESEAL (1) SWEEP (1) DAM STRIP		

ARROW MIRROR & GLASS