


# INSTALLATION SHEET

Project Name: V80 IL DR NS MBL CLR AGI3

8/17/2023

## 3D VIEW




Customer: DAVID-ADG

Location: 9602 PINK

Quantity: 1


Project #: 10072723-T-B2

## OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

## GLASS SIZES AND CLEARANCES



## INSTALLATION COMMENTS

### HARDWARE:

- ( 2 ) V HINGES
- ( 1 ) V HANDLE
- ( 2 ) V CLIPS

### PLASTICS:

- ( 1 ) STRIKER
- ( 1 ) DAM STRIP
- ( 1 ) SWEEP
- ( 1 ) HINGE SEAL