
INSTALLATION SHEET Project Name: V80 90 DL SS MBL CLR AGI2 10/4/2023



15-1/16


Customer: DAVID-06

Location: 15222 PARKLAND

Quantity: 1

Project #: 10075813-A-MB

OUT OF PLUMB / LEVEL CONDITIONS




GLASS SIZES AND CLEARANCES


Showing Centerline Void

28-11/16

11-1/8



JUNCTIONS



Exterior

INSTALLATION COMMENTS

HARDWARE:

(2) V HINGES

INSTALLATION SHEET	Project Name: V80 90 DL SS MBL CLR AGI2	10/4/2023
(1) V HANDLE (4) V CLIPS		
PLASTICS: (1) STRIKER (1) HINGESEAL (1) SWEEP (1) DAM STRIP (1) GROUT GUARD		