


INSTALLATION SHEET

Project Name: R PANEL BN (OT/OR) CLR


10/4/2023

3D VIEW




Customer: DAVID-06
Location: 988 TERLINGUA
Quantity: 1
Project #: 10075822-B-MBP1

OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

GLASS SIZES AND CLEARANCES



INSTALLATION COMMENTS

HARDWARE:
(3) R CLIP

PLASTICS:
(1) GROUT GUARD