


INSTALLATION SHEET

Project Name: V70 IL DL NS CH CLR AGI2


9/13/2023

3D VIEW




Customer: FIRST-ADG
Location: 25367 LEATHER
Quantity: 1
Project #: 10074404-B-MB

OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

GLASS SIZES AND CLEARANCES



INSTALLATION COMMENTS

HARDWARE:

- (2) V HINGES
- (1) V HANDLE
- (1) V CLIPS

PLASTICS:

- (1) STRIKER
- (1) DAM STRIP
- (1) SWEEP
- (1) HINGE SEAL