

INSTALLATION SHEET Project Name: V80 90 DR SS CH CLR AGI3 7/26/2023 3D VIEW Customer: DFH-ADG Location: 7307 COMPASS Quantity: 1




Project #: 10070855-H-MB

OUT OF PLUMB / LEVEL CONDITIONS




Showing Centerline Void

GLASS SIZES AND CLEARANCES



JUNCTIONS



Exterior

INSTALLATION COMMENTS

HARDWARE:

(2) V HINGES

(1) STRIKER (1) HINGESEAL (1) SWEEP	INSTALLATION SHEET	Project Name: V80 90 DR SS CH CLR AGI3	7/26/2023
PLASTICS: (1) STRIKER (1) HINGESEAL (1) SWEEP (1) DAM STRIP	(1) V HANDLE (4) V CLIPS		
	(1) STRIKER (1) HINGESEAL (1) SWEEP		

ARROW MIRROR & GLASS