
INSTALLATION SHEET Project Name: V80 90 DR SS CH CLR AGI2 7/26/2023






Customer: DDFH-ADG Location: 20415 SCOUT

Quantity: 1


Project #: 10071406-I-MB

OUT OF PLUMB / LEVEL CONDITIONS




Showing Centerline Void

GLASS SIZES AND CLEARANCES



JUNCTIONS



Exterior

INSTALLATION COMMENTS

HARDWARE:

(2) V HINGES

INSTALLATION SHEET	Project Name: V80 90 DR SS CH CLR AGI2	7/26/2023
(1) V HANDLE (3) V CLIPS		
PLASTICS: (1) STRIKER (1) HINGESEAL (1) SWEEP (1) DAM STRIP		

ARROW MIRROR & GLASS