


INSTALLATION SHEET

Project Name: R PANEL BN (OT/OL) CLR

10/4/2023

3D VIEW




Customer: DAVID-06

Location: 988 TERLINGUA

Quantity: 1


Project #: 10075822-B-MBP2

OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

GLASS SIZES AND CLEARANCES



INSTALLATION COMMENTS

HARDWARE:

(3) R CLIP

PLASTICS:

(1) GROUT GUARD