


INSTALLATION SHEET

Project Name: V80 90 DR SS MBL CLR AGI3

10/4/2023

3D VIEW




Customer: DAVID-06

Location: 21614 SHAKE

Quantity: 1


Project #: 10075743-A-MB

OUT OF PLUMB / LEVEL CONDITIONS




Showing Centerline Void

GLASS SIZES AND CLEARANCES



JUNCTIONS



INSTALLATION COMMENTS

HARDWARE:
(2) V HINGES

INSTALLATION SHEET

Project Name: V80 90 DR SS MBL CLR AGI3

10/4/2023

(1) V HANDLE

(4) V CLIPS

PLASTICS:

(1) STRIKER

(1) HINGE SEAL

(1) SWEEP

(1) DAM STRIP

(1) GROUT GUARD