


INSTALLATION SHEET

Project Name: V80 IL DR NS BN CLR AGI3

10/4/2023

3D VIEW




Customer: DAVID-06

Location: 2415 TEXAS

Quantity: 1


Project #: 10074021-I-B2

OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

GLASS SIZES AND CLEARANCES



INSTALLATION COMMENTS

HARDWARE:

- (2) V HINGES
- (1) V HANDLE
- (2) V CLIPS

PLASTICS:

- (1) STRIKER
- (1) DAM STRIP
- (1) SWEEP
- (1) HINGE SEAL