
INSTALLATION SHEET

Project Name: V72 IL DR NS BN CLR

8/17/2023

3D VIEW




Customer: CHESMAR HOMES-ADG Location: 13326 PINE LAKE BEND

Quantity: 1


Project #: 10072460-C-MB-RE1

OUT OF PLUMB / LEVEL CONDITIONS



Showing Centerline Void

GLASS SIZES AND CLEARANCES



INSTALLATION COMMENTS

08.15 REMAKE DOOR BROKE