AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 3/24/2026, 10:38:28 AM

Vehicle Information

Make & Model: Honda Civic
Year: 2017
Number Plate: N/A
Project ID: 69ba3189643d927d92aac267

Incident Details

Driver Name: John Doe
Driver License: DL - 8765436789
Description: wsedfrtghuihiyhiyhyh
Witnesses: N/A

Damage Analysis & Cost Estimation

Damaged Part	Estimated Cost (INR)
fender-dent	₹4,000 - ₹15,000
front-bumper-dent	₹4,000 - ₹15,000
quaterpanel-dent	₹6,000 - ₹12,000
rear-bumper-dent	₹4,000 - ₹15,000
doorouter-dent	₹4,000 - ₹9,000
bonnet-dent	₹5,000 - ₹18,000
roof-dent	₹7,000 - ₹20,000
Windscreen-Damage	₹6,000 - ₹18,000
boot-dent	₹5,000 - ₹18,000
RunningBoard-Dent	₹3,500 - ₹8,000

Total Consolidation: ₹48,500 - ₹148,000

Authorized By (Digital Signature)

Nitheesh B