AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 3/19/2026, 12:19:41 AM

Vehicle Information

Make & Model: Honda Civic
Year: 2017
Number Plate: N/A
Project ID: 69ba3189643d927d92aac267

Incident Details

Driver Name: John Doe
Driver License: DL - 8765436789
Description: Andheri, August 21: Two persons died and two more were injured when a speeding lorry had a head on collision with a car yesterday at around 5 p.m. near Andheri. It was office time and the crossing of Andheri was crowded as usual. Mr. Sharma, an eyewitness of the accident, reported that while overtaking a bus, the speeding lorry hit a private car which was coming from the opposite direction. The driver and the man sitting next to him died on the spot. Two persons sitting at the back seat got severely injured. The locals rushed to the spot and took the injured to the nearby hospital. The accident brought the traffic to a standstill. An investigation has been demanded as how a lorry was allowed to ply at that hour of the day. The administration has promised to look into the matter.
Witnesses: N/A

Damage Analysis & Cost Estimation

Damaged Part	Estimated Cost (INR)
fender-dent	₹4,000 - ₹15,000
front-bumper-dent	₹4,000 - ₹15,000
quaterpanel-dent	₹6,000 - ₹12,000
rear-bumper-dent	₹4,000 - ₹15,000
doorouter-dent	₹4,000 - ₹9,000
bonnet-dent	₹5,000 - ₹18,000
roof-dent	₹7,000 - ₹20,000

Windscreen-Damage	₹6,000 - ₹18,000
boot-dent	₹5,000 - ₹18,000
RunningBoard-Dent	₹3,500 - ₹8,000

Total Consolidation: ₹48,500 - ₹148,000

Authorized By (Digital Signature)

Nitheesh B