AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 4/13/2026, 12:21:21 AM

Vehicle Information

Make & Model: BMW 520d
Year: 2019
Number Plate: KL66D4156
Project ID: 69c958f9a1ba3bde28e7bf46

Incident Details

Driver Name: Noel Martin
Driver License: DL - 1234567898
Description: qwerftg
Witnesses: N/A

Damage Analysis & Cost Estimation

Damaged Part	Qty	Estimated Unit Cost	Total Estimated Cost
rear-bumper-dent	1	₹8,000 - ₹25,000	₹8,000 - ₹25,000
front-bumper-dent	1	₹8,000 - ₹25,000	₹8,000 - ₹25,000
quaterpanel-dent	1	₹15,000 - ₹40,000	₹15,000 - ₹40,000
fender-dent	1	₹7,000 - ₹22,000	₹7,000 - ₹22,000
Windscreen-Damage	2	₹35,000 - ₹70,000	₹70,000 - ₹140,000
doorouter-dent	1	₹8,000 - ₹25,000	₹8,000 - ₹25,000

Total Consolidation: ₹116,000 - ₹277,000

Authorized By (Digital Signature)

Alan Varghese