AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 4/12/2026, 11:24:17 PM

Vehicle Information

Make & Model: Honda Civic
Year: 2017
Number Plate: KL66C2413
Project ID: 69ba3189643d927d92aac267

Incident Details

Driver Name: Joyal Jamess
Driver License: DL- 2345678901
Description: A complete incident report template must capture six categories of information: incident identification, people involved, a factual description, injury and damage details, immediate actions taken, and corrective follow-up measures. Missing any of these creates gaps during investigations, insurance claims, and regulatory audits. Three publicly available templates from OSHA, CISA, and CMS provide tested starting points that reflect current regulatory standards. OSHA Form 301 is the most widely recognized for workplace injuries, while the CISA and CMS templates extend to cybersecurity and healthcare contexts. For teams still relying on paper forms, digital tools like Alpha TransForm, SafetyCulture, and Freshservice can automate data capture, routing, and trend analysis.
Witnesses: N/A

Damage Analysis & Cost Estimation

Damaged Part	Qty	Estimated Unit Cost	Total Estimated Cost
fender-dent	2	₹3000 - ₹6500	₹6,000 - ₹13,000
front-bumper-dent	1	₹2500 - ₹6000	₹2,500 - ₹6,000
quaterpanel-dent	2	₹4000 - ₹8500	₹8,000 - ₹17,000
rear-bumper-dent	1	₹2500 - ₹6000	₹2,500 - ₹6,000
doorouter-dent	4	₹3000 - ₹7000	₹12,000 - ₹28,000
bonnet-dent	1	₹3500 - ₹7500	₹3,500 - ₹7,500
roof-dent	1	₹7,000 - ₹20,000	₹7,000 - ₹20,000
Windscreen-Damage	1	₹6,000 - ₹18,000	₹6,000 - ₹18,000

boot-dent	1	₹5,000 - ₹18,000	₹5,000 - ₹18,000
RunningBoard-Dent	1	₹4,000 - ₹12,000	₹4,000 - ₹12,000
Headlight-Damage	1	Estimation unavailable	Estimation unavailable

Total Consolidation: ₹56,500 - ₹145,500

Authorized By (Digital Signature)

Nitheesh B