AutoInspect AI

Official Vehicle Damage Assessment Report

Generated on: 4/13/2026, 12:17:25 AM

Vehicle Information

Make & Model: Toyota Corolla
Year: 2020
Number Plate: KL66D5757
Project ID: 69dbe42d49adddf28472a2b8

Incident Details

Driver Name: Noel Martin
Driver License: DL - 1234567898
Description: wftghnj
Witnesses: N/A

Damage Analysis & Cost Estimation

Damaged Part	Qty	Estimated Unit Cost	Total Estimated Cost
fender-dent	2	₹4,500 - ₹7,500	₹9,000 - ₹15,000
front-bumper-dent	1	₹5,000 - ₹9,000	₹5,000 - ₹9,000
quaterpanel-dent	2	₹6,000 - ₹10,000	₹12,000 - ₹20,000
rear-bumper-dent	1	₹5,000 - ₹9,000	₹5,000 - ₹9,000
doorouter-dent	4	₹4,000 - ₹7,000	₹16,000 - ₹28,000
Headlight-Damage	1	₹12,000 - ₹22,000	₹12,000 - ₹22,000
bonnet-dent	1	₹8,000 - ₹15,000	₹8,000 - ₹15,000
Taillight-Damage	1	₹4,000 - ₹8,000	₹4,000 - ₹8,000
boot-dent	1	₹6000 - ₹12000	₹6,000 - ₹12,000
roof-dent	1	₹10000 - ₹20000	₹10,000 - ₹20,000
Windscreen-Damage	1	₹8,000 - ₹15,000	₹8,000 - ₹15,000
Sidemirror-Damage	1	₹4,000 - ₹8,500	₹4,000 - ₹8,500

Total Consolidation: ₹99,000 - ₹181,500

Authorized By (Digital Signature)

Aloke Saji