Fake04 synthetic evidence - 02_field_survey - page 1

North: no surveyed facilities within 2.0H above the crest or 2.0H below the road.

North section N1: three boreholes; zero test pits; no geophysics performed.

North: N1 is the only investigation section.

North: investigation of geology and groundwater is adequate to select calculation parameters.

No groundwater was encountered in the North N1 boreholes down to 15 m on 2026-03-21.

South: field survey located a water tank 0.4H upslope from the cut crest.

South: survey of investigation sections and exploration point counts is unavailable.

South: no facilities found within 0.2H above the cut crest and 0.2H below the road.