

WDFW Fish Passage and Diversion Screening Inventory Database

Site Description Report

Site ID 115 TC129

Project FBRB

☐ Mitigated

Geographic Coordinates

Latitude (WGS 84):	46.95631
Longitude (WGS 84):	-122.79684
East (NAD 83 HARN):	1,066,944.8
North (NAD 83 HARN):	600,201.2

Waterbody

Stream:	Spurgeon Cr
Tributary To:	Deschutes R
WRIA:	13.0037
River Mile:	-999.99
Fish Use Potential:	Yes
FUP Criteria:	Mapped

General Location

Road Name:	Equus Ln SE
Mile Post:	-999.99
County:	Thurston
WDFW Region:	

Owner

Type:	Private
Name:	Shroeder

PI Species

☐ Sockeye	☒ Chinook	☒ Sea Run Cutthroat
☐ Pink	☒ Coho	☒ Resident Trout
☒ Chum	☒ Steelhead	☐ Bull Trout

Associated Features

☒ Culvert	☐ Dam	☐ Natural Barrier	☐ Diversion
☐ Non-Culvert Xing	☐ Other	☐ Fishway	

Location/Directions

Drive Yelm Hwy east, right on Rainier Rd., right on 89th Ave SE.

Site Comments

11/19/2021

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level A Culvert Assessment Report

Site ID: **115 TC129**
 Latitude: **46.95631** Stream: **Spurgeon Cr** WRIA: **13.0037**
 Longitude: **-122.79684** Tributary To: **Deschutes R** Fish Use Potential: **Yes**

Data Source: Washington Department of Fish and Wildlife

Field Crew: Paulus;Tuttle

Review Date: 4/16/2018

Culvert Details

Level A Parameters

ID	Shape	Material	Span	Rise	Length	WDIC	Apron	WSDrop	Location	Countersunk	Backwater	Slope (%)	Sediment
1.2	RND	CST	1.07	1.07	15.70	0.52	NO	0.00		No	No	0.19	
2.2	RND	CST	1.07	1.07	15.70	0.45	NO	0.00		No	No	0.00	

All dimensions in meters

Channel Description

Toe Width (m): -99.99

Average Width (m): 10.50

Culvert/Stream Width Ratio: 0.20

Plunge Pool

Length (m): 0.00

Max Depth (m): -99.99

OHW Width (m): -999.99

Road

Fill Depth (m): 2.00



Assessment Results

Tidal Influence:

Tidegate Present:

No

Barrier: Yes

Passability (%):

67

Method:

Level B

Reason: Depth

Fishway Present:

No

Recheck:

Comments

[Lvl B-Paulus, 04/17/2018, HY-8, V&D from 1.2]

Potential Habitat Gain

Survey Type:

Spawning (sq m):

Length (m):

Significant Reach: Yes

Rearing (sq m):

PI Total

11/19/2021

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level B Culvert Assessment Report

Site ID: 115 TC129

Reference Point

Elevation (m): 100.00 Location: 1.2 US invert

Drainage Basin

Basin Area (sq mi): 3.95 Basin Precipitation (in): 45.70

Culvert Elevations

Culvert ID	Corrugation	USIE (m)	USCBE (m)	DSIE (m)	DSCBE (m)	Sediment
1.2	0.5"x2.66"	100.00	-999.99	99.97	-999.99	
2.2	0.5"x2.66"	99.99	-999.99	99.99	-999.99	

Downstream Control

X-Section

Station	Top LB	Toe LB	Bed 1	Bed 2	Bed 3	Toe RB	Top RB
Distance (m)	0.00	0.45	7.00	11.00	14.50	16.30	16.90
Elevation (m)	100.54	100.42	100.06	100.17	100.07	100.32	100.67
Substrate							

Downstream Control Water Surface Elevation (m): 100.50

Downstream Control OHW Surface Elevation (m): -999.99

Downstream of Control

Water Surface Elevation (m): 100.49 Channel Dominant Substrate: Gravel

Distance Downstream (m):

Results

Velocity (m/sec): 1.37 Depth (m): 0.24

11/19/2021

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database
Image Report - Active

Site ID: **115 TC129**

Latitude: **46.95631**

Longitude: **-122.79684**

Stream: **Spurgeon Cr**

Tributary To: **Deschutes R**

WRIA: **13.0037**

Fish Use Potential: **Yes**

Associated Features

☒ Culvert

☐ Dam

☐ Natural Barrier

☐ Diversion

☐ Non-Culvert Xing

☐ Other

☐ Fishway



11/19/2021

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.