

WDFW Fish Passage and Diversion Screening Inventory Database

Site Description Report

Site ID

Project

☐ Mitigated

Geographic Coordinates

Latitude (WGS 84):	46.9528618
Longitude (WGS 84):	-122.7807236
East (NAD 83 HARN):	1,070,925.9
North (NAD 83 HARN):	598,839.0

Waterbody

Stream:	Spurgeon Cr
Tributary To:	Deschutes R
WRIA:	13.0037
River Mile:	-999.99
Fish Use Potential:	Yes
FUP Criteria:	Biological

General Location

Road Name:	Rainier Rd SE
Mile Post:	6.49
County:	Thurston
WDFW Region:	6

Owner

Type:	County
Name:	Thurston County

PI Species

☐ Sockeye	☐ Chinook	☒ Sea Run Cutthroat
☐ Pink	☒ Coho	☒ Resident Trout
☐ Chum	☒ Steelhead	☐ Bull Trout

Associated Features

☒ Culvert	☐ Dam	☐ Natural Barrier	☐ Diversion
☐ Non-Culvert Xing	☐ Other	☐ Fishway	

Location/Directions

Site Comments

Channelized wetland on both ends of pipe. Unknown juvenile salmonid species observed on DS.

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level A Culvert Assessment Report

Site ID: **342433**
Latitude: **46.9528618** Stream: **Spurgeon Cr** WRIA: **13,0037**
Longitude: **-122.7807236** Tributary To: **Deschutes R** Fish Use Potential: **Yes**

Data Source: Washington Department of Fish and Wildlife

Field Crew: Anderson;Harris

Review Date: 7/30/2024

Culvert Details

Level A Parameters

ID	Shape	Material	Span	Rise	Length	WDIC	Apron	WSDrop	Location	Countersunk	Backwater	Slope (%)	Sediment
1.2	SQSH	CST	1.60	1.00	21.80	0.65	NO	0.00		No	Yes	0.32	No
2.2	SQSH	CST	1.60	1.00	20.60	0.83	NO	0.00		No	Yes	0.39	Yes

All dimensions in meters

Channel Description

Toe Width (m): -99.99

Average Width (m): 3.58

Culvert/Stream Width Ratio: 0.89

Plunge Pool

Length (m): 0.00

Max Depth (m): -99.99

OHW Width (m): -999.99

Road

Fill Depth (m): 3.00



Assessment Results

Tidal Influence: No

Tidegate Present: No

Barrier: No

Passability (%): 100

Method: Level B

Reason: N/A

Fishway Present: No

Recheck:

Comments

[LvlB-Harris, 7/30/2024, HY-8. V&D from 1.2. Depth N/A. Qfp=0.87 cms] Rebar set vertically into both inlets acting as a debris rack. Gapping >0.30m, no concerns for fish passage.

Potential Habitat Gain

Survey Type:

Spawning (sq m):

Length (m):

Significant Reach: Unknown

Rearing (sq m):

PI Total:

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level B Culvert Assessment Report

Site ID:

Reference Point

Elevation (m): Location:

Drainage Basin

Basin Area (sq mi): Basin Precipitation (in):

Culvert Elevations

<u>Culvert ID</u>	<u>Corrugation</u>	<u>USIE (m)</u>	<u>USCBE (m)</u>	<u>DSIE (m)</u>	<u>DSCBE (m)</u>	<u>Sediment</u>
1.2	<input type="text" value="1" x3"=""/>	100.08	100.15	100.26	100.33	No
2.2	<input type="text" value="1" x3"=""/>	100.00	100.08	99.99	100.05	Yes

Downstream Control

X-Section

<u>Station</u>	<u>Top LB</u>	<u>Toe LB</u>	<u>Bed 1</u>	<u>Bed 2</u>	<u>Bed 3</u>	<u>Toe RB</u>	<u>Top RB</u>
Distance (m)	0.00	3.05	4.90	6.50	8.10	9.65	10.50
Elevation (m)	101.05	100.45	100.01	100.15	100.22	100.68	101.03
Substrate	Mud	Gravel	Mud	Mud	Mud	Mud	Mud

Downstream Control Water Surface Elevation (m):

Downstream Control OHW Surface Elevation (m):

Downstream of Control

Water Surface Elevation (m): Channel Dominant Substrate:

Distance Downstream (m):

Results

Velocity (m/sec): Depth (m):

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Image Report - Active

Site ID: **342433**

Latitude: **46.9528618**

Longitude: **-122.7807236**

Stream: **Spurgeon Cr**

Tributary To: **Deschutes R**

WRIA: **13.0037**

Fish Use Potential: **Yes**

Associated Features

☒ Culvert

☐ Dam

☐ Natural Barrier

☐ Diversion

☐ Non-Culvert Xing

☐ Other

☐ Fishway



Image Name: 342433_1.jpg



Image Name: 342433_2.jpg

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.