



Washington Department of Fish and Wildlife

Fish Passage & Diversion Screening Inventory Database Report Cover Sheet

The following report is extracted from the Washington Department of Fish and Wildlife's (WDFW) Fish Passage and Diversion Screening Inventory Database (FPDSI). WDFW makes every attempt to keep these reports in sync with FPDSI; however, the dynamic nature of the data and workflows associated with maintaining the database may result in short-term differences.

Users are encouraged to contact WDFW to discuss appropriate use of the data and how we can assist with fish passage barrier removal or inventory. Please visit the Fish Passage web site for contact information at: <https://wdfw.wa.gov/species-habitats/habitat-recovery/fish-passage/about>

Disclaimers:

- Data presented here represent a snapshot observation of conditions in a dynamic environment that is subject to change. Fish passage data are also collected from a variety of agencies and sources. Therefore, WDFW makes no guarantee concerning the data's content, accuracy, completeness, or the results obtained from use of the data. WDFW assumes no liability for the data represented here.
- These data are not an attempt to provide you with an official agency response as to the impacts of your project on fish and wildlife.
- Note that some fish passage features, habitats or species may occur in areas not currently known to the WDFW Fish Passage division, and may not be reflected in this database. A lack of data does not necessarily indicate that a feature, habitat, or species are not present.
- Unauthorized attempts to alter or modify these data are strictly prohibited.
- Bankfull width measurements included in these reports should not be used for fish passage crossing design. They are solely for assessment purposes.
- The barrier status reported in this document is based on the swimming abilities of adult salmonids. Passabilities are a qualitative value, and should not be interpreted as a quantitative calculation. Please see page 1-4 of the Fish Passage Inventory, Assessment and Prioritization Manual for further clarification: <https://wdfw.wa.gov/publications/02061>
- EXIF data presented with Image Reports may be erroneous due to camera battery failures and resetting of camera clock functions.

Abbreviations:

Most abbreviations in this report are defined in the Quick Reference Tables of the Fish Passage Inventory, Assessment, and Prioritization Manual. Additional commonly used abbreviations are defined as follows:

NFB = no potential salmonid use, **BB** = both banks, **LB** = left bank looking downstream, **RB** = right bank looking downstream, **US** or **U/S** = upstream, **DS** or **D/S** = downstream, **WSDrop** = water surface drop, **BFW** = bankfull width, **OHW** = ordinary high water, **SLW** = scour line width, **CMP** = corrugated metal pipe, **Q_{fp}** = fish passage flow, **V&D** = Velocity and Depth, **ROW** = Right of Way

The FPDSI database often uses default values such as '-99.99' or '-999' to represent null values.

WDFW Fish Passage and Diversion Screening Inventory Database

Site Description Report

Site ID 342433

Project COUNTY

☐ Mitigated

Geographic Coordinates

Latitude (WGS 84): 46.9528618
Longitude (WGS 84): -122.7807236
East (NAD 83 HARN): 1,070,925.9
North (NAD 83 HARN): 598,839.0

Waterbody

Stream: Spurgeon Cr
Tributary To: Deschutes R
WRIA: 13.0037
River Mile: -999.99
Fish Use Potential: Yes
FUP Criteria: Biological

General Location

Road Name: Rainier Rd SE
Mile Post: 6.49
County: Thurston
WDFW Region: 6

Owner

Type: County
Name: Thurston County

PI Species

☐ Sockeye ☐ Chinook ☒ Sea Run Cutthroat
☐ Pink ☒ Coho ☒ Resident Trout
☐ Chum ☒ Steelhead ☐ Bull Trout

Associated Features

☒ Culvert ☐ Dam ☐ Natural Barrier ☐ Diversion
☐ Non-Culvert Xing ☐ Other ☐ Fishway

Location/Directions

.115 mi NW of STEDMAN RD SE

Site Comments

Channelized wetland on both ends of pipe. Unknown juvenile salmonid species observed on DS.

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level A Culvert Assessment Report

Site ID: **342433**
 Latitude: **46.9528618** Stream: **Spurgeon Cr** WRIA: **13.0037**
 Longitude: **-122.7807236** Tributary To: **Deschutes R** Fish Use Potential: **Yes**

Data Source: Washington Department of Fish and Wildlife

Field Crew: Anderson;Harris

Review Date: 7/30/2024

Culvert Details

ID	Shape	Material	Span	Rise	Length	WDIC	Apron	WSDrop	Location	Countersunk	Backwater	Slope (%)	Sediment
1.2	SQSH	CST	1.60	1.00	21.80	0.65	NO	0.00		No	Yes	0.32	No
2.2	SQSH	CST	1.60	1.00	20.60	0.83	NO	0.00		No	Yes	0.39	Yes

All dimensions in meters

Channel Description

Toe Width (m): -99.99

Average Width (m): 3.58

Culvert/Stream Width Ratio: 0.89

Plunge Pool

Length (m): 0.00

Max Depth (m): -99.99

OHW Width (m): -999.99

Road

Fill Depth (m): 3.00



Assessment Results

Tidal Influence: No

Tidegate Present: No

Barrier: No

Passability (%): 100

Method: Level B

Reason: N/A

Fishway Present: No

Recheck:

Comments

[Lv/B-Harris, 7/30/2024, HY-8. V&D from 1.2. Depth N/A. Qfp=0.87 cms] Rebar set vertically into both inlets acting as a debris rack. Gapping >0.30m, no concerns for fish passage.

Potential Habitat Gain

Survey Type:

Spawning (sq m):

Length (m):

Significant Reach: Unknown

Rearing (sq m):

PI Total

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Level B Culvert Assessment Report

Site ID:

Reference Point

Elevation (m): Location:

Drainage Basin

Basin Area (sq mi): Basin Precipitation (in):

Culvert Elevations

Culvert ID	Corrugation	USIE (m)	USCBE (m)	DSIE (m)	DSCBE (m)	Sediment
1.2	<input type="text" value="1" x3"=""/>	100.08	100.15	100.26	100.33	No
2.2	<input type="text" value="1" x3"=""/>	100.00	100.08	99.99	100.05	Yes

Downstream Control

X-Section							
Station	Top LB	Toe LB	Bed 1	Bed 2	Bed 3	Toe RB	Top RB
Distance (m)	0.00	3.05	4.90	6.50	8.10	9.65	10.50
Elevation (m)	101.05	100.45	100.01	100.15	100.22	100.68	101.03
Substrate	Mud	Gravel	Mud	Mud	Mud	Mud	Mud

Downstream Control Water Surface Elevation (m):

Downstream Control OHW Surface Elevation (m):

Downstream of Control

Water Surface Elevation (m): Channel Dominant Substrate:

Distance Downstream (m):

Results

Velocity (m/sec): Depth (m):

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.

WDFW Fish Passage and Diversion Screening Inventory Database

Image Report - Active

Site ID: **342433**

Latitude: **46.9528618**

Longitude: **-122.7807236**

Stream: **Spurgeon Cr**

Tributary To: **Deschutes R**

WRIA: **13.0037**

Fish Use Potential: **Yes**

Associated Features

☒ Culvert

☐ Dam

☐ Natural Barrier

☐ Diversion

☐ Non-Culvert Xing

☐ Other

☐ Fishway



Image Name: 342433_1.jpg



Image Name: 342433_2.jpg

11/4/2024

These data represent a snapshot of the Washington Department of Fish and Wildlife's current records. Due to the ongoing nature of assessment and inventory of these features, these data may not accurately represent conditions on the ground, and are subject to change.