

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL

NEE SOON TOWN COUNCIL

LOCATION

NEE SOON LINK DIVISION

DATE OF SERVICING

29 /09/2025

MONTHLY HOSEREEL SYSTEM CHECKLIST REPORT

1. HOSEREEL

- 1.1 Check hoses remain unobstructed
- 1.2 Ensure hoses are available for use at all times
- 1.3 Check hose reel cabinet, hose reel and rubber hose for damage
- 1.4 Inspect the stop valves, glands, pipings and shut-off nozzles are free from leak
- 1.5 Check & verify operation of stop valve at hose reel pipe & ensure valve is fully closed
- 1.6 Check operation of nozzle and stopcock for blockage


Block No :

430B	431	431A	431B	431C	431D
☒	☒	☒	☒	☒	☒
☒	☒	☒	☒	☒	☒
☒	☒	☒	☒	☒	☒
☒	☒	☒	☒	☒	☒
☒	☒	☒	☒	☒	☒
☒	☒	☒	☒	☒	☒

REMARKS

Name & signature of Technician(s)

Verified By :

1 

2 _____

(Name & signature)

Oct 03, 2024, 11:28

Blk 431A level 8 2-2
Door can't open

**DRY RISING
MAIN OUTLET 2-2
FIRE HOSE REEL**

Turn on inlet valve before running out hose



**RED POWER
MANI**

19:31 Tues
16/09/2025

■ Hassan Barber Pte Ltd, 431A
Yishun Avenue 1, 761431

Timemark App
Authentic time, GPS

YE3BTLYN6XXYGED Timemark Verified

Aug 20, 2025, 15:21

BIK 431A #12 2-2 Nozzle Box Glass Broken



**RED POWER
MANI**

19:26 Tues
16/09/2025

■ Hassan Barber Pte Ltd, 431A
Yishun Avenue 1, 761431

Timemark App
Authentic time, GPS

DB9AUPCD9A2YYG Timemark Verified

Aug 20, 2025, 15:21

BIK 431C #5 2-2 Nozzle Box Glass Broken



**RED POWER
MANI**

19:58 Tues
16/09/2025

■ Vista Spring, 431C Yishun
Avenue 1, 763431

Timemark App
Authentic time, GPS

© R6NAP2Y6HACXRD Timemark Verified