

RED-POWER ELECTRICAL ENGINEERING PTE LTD

BLK 16 DEFU LANE 10. #01 - 364. SINGAPORE 539197

TEL : 6 289 2298

FAX : 6 287 9635

TOWN COUNCIL

NEE SOON TOWN COUNCIL

LOCATION

NEE SOON LINK DIVISION

DATE OF SERVICING

28 /09/2025

MONTHLY HOSEREEL SYSTEM CHECKLIST REPORT

1. HOSEREEL

- 1.1 Check hoses remain unobstructed
- 1.2 Ensure hoses are available for use at all times
- 1.3 Check hose reel cabinet, hose reel and rubber hose for damage
- 1.4 Inspect the stop valves, glands, pipings and shut-off nozzles are free from leak
- 1.5 Check & verify operation of stop valve at hose reel pipe & ensure valve is fully closed
- 1.6 Check operation of nozzle and stopcock for blockage

Block No :

468	468A	469A	469B	470A	470B
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/
/	/	/	/	/	/

REMARKS

Name & signature of Technician(s)

Verified By :

1 Selwa

(Name & signature)

2 _____

Blk 468A #3 1-4

Door can't open

DRY RISING MAIN OUTLET 1-4

FIRE HOSE REEL

Turn on the inlet valve before running out the hose

IMPORTANT REMINDER



NSE


Hosereel drum

19:17 Thurs
18/09/2025

- **Work Content: Door can't open**
- **Meadow Spring @ Yishun,
468A Yishun Street 43,
761468**

Timemark App
Authentic time, GPS

Blk 469A #2 1-2
hosereel nozzle box
glass broken



NSE

Hosereel drum

19:38 Thurs
18/09/2025

- Work Content: Door can't open
- 469a Yishun Street 43

Timemark App
Authentic time, GPS

Blk 469A #6 1-2

Door can't open

DRY RISING MAIN OUTLET 1-2

FIRE HOSE REEL

Turn on the inlet valve before running out the hose



NSE

Hosereel drum

19:35 Thurs
18/09/2025

- Work Content: Door can't open
- 469a Yishun Street 43

Timemark App
Authentic time, GPS



NSTC NSS
HR pump

19:45 Thurs, 18/09/2025

- Forest Spring @ Yishun, 470B Yishun Street 42, 762470
- Job: Fire Hs mirror broken Lvl 01

Timemark App
Authentic time, GPS