

WHEEL LOADER: SAFETY & MAINTENANCE



Executive Summary Report

Inspection No	22892110	Inspector	John Doe
Serial Number	5678	Date Generated	2026-02-28
Model	CAT 950	SMU (Hours)	1027 Hours
Asset ID	FL-3062	Location	East Peoria, IL

General Info & Comments
Scales screen freezes during operation

GROUND		
Component	Status	Observations / Comments
1. Air Tank	PASS	
2. Axles Brakes Seals	PASS	
3. Battery Compartment	PASS	
4. Bucket Cutting Edge Moldboard	PASS	
5. Bucket Cylinders Lines Hoses	PASS	
6. Def Tank	PASS	
7. Differential Final Drive Oil	PASS	
8. Fuel Tank	PASS	
9. Hydraulic Tank	PASS	
10. Lights Front Rear	PASS	
11. Loader Frame Arms	PASS	
12. Overall Machine	PASS	
13. Steps Handholds	PASS	
14. Tires Wheels Stem Caps Lug Nuts	PASS	
15. Transmission Oil	PASS	
16. Transmission Transfer Case	PASS	
17. Underneath Machine	PASS	
ENGINE		

Component	Status	Observations / Comments
1. Air Filter	PASS	
2. All Belts	PASS	
3. All Hoses And Lines	PASS	
4. Engine Coolant	PASS	
5. Engine Oil	PASS	
6. Fuel Filters Water Separator	PASS	
7. Overall Engine Compartment	PASS	
8. Radiator	PASS	

CAB INTERIOR

Component	Status	Observations / Comments
1. Cab Air Filter	PASS	
2. Gauges Indicators Switches	PASS	
3. Horn Alarm Lights	PASS	
4. Mirrors	PASS	
5. Overall Cab Interior	PASS	
6. Seat	MONITOR	needs upholstery
7. Seat Belt Mounting	PASS	

CAB EXTERIOR

Component	Status	Observations / Comments
1. Doors	PASS	
2. Fire Extinguisher	PASS	
3. Handholds	PASS	
4. Rops	PASS	
5. Windshield Windows	PASS	
6. Wipers Washers	PASS	