

Atco



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 7/8/2011Requested by SwathyDepartment Ward Location SA

SR. No.	Machine	Model	Complaint
P770B1404 0003	DVT machine	DVT-7700	Socket complaint

Check within ☐ Week☐ ASAP

Engineer Comments

End Comments

Requested by _____

Checked By _____

Approved by _____

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجبراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 61604

Customer	Aloft Hospital	Equipment	DUT Machine.
		Model No.	DUT-7700
		Serial No.	P770B 1404003
Authorized Person		Manufacturer	wonjin
Customer Complaint		Location	
	Socket Complaint	Contract / Order No.	

Services / Check Carried out	☐ Installation	☐ Warranty
	☐ Repair	☐ On Charge
☐ Inspection / Cleaning	☐ Maintenance	☐ Contract
☐ Calibration / Performance	☐ Upgrade	☐
☐ Interface / Communication		
☐ Safety Checks		
☐ Electrical / Electronics		
☐ Accessories Check		
☐ Optics Checks		
☐ Pneumatic Checks		
☐ Hydraulic Checks		
☐ Operational Error		
☐ Mechanical Checks		
☐		

Remarks	Service call attended
	We inspect the unit and tested the pressure.
	We found that both ports are working.
	also checked the Power socket.
	We couldn't find any issue with the unit.

No.	Spare Parts Used	Part No.	Qty.

Service Engineer	Authorized Person	Customer / User
Signature	Signature	Signature
Date	Date	Date
11/08/2024	11/8/2024	