

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 29/12/2024

Requested by Dr. Amr

Department Ophthalmology Location 5th floor old

SR. No.	Machine	Model	Complaint
<u>2632794</u>	<u>Computerized tonometer</u>	<u>CT-1P</u>	<u>Chin rest not working</u>

Check within Week

☒ ASAP

Engineer Comments

End Comments

Honey
Requested by

Checked By

Approved by



NO. 0788	SERVICE REPORT	PAGE /
CUSTOMER <u>AL ORF Hospital</u>	DATE <u>29-12-2024</u>	
LOCATION <u>OPD, 5th Floor, Dr. Amr Clinic</u>		
EQUIPMENT <u>Computerized Tonometer.</u>		
MANUFACTURE <u>Topcon</u>		
MODEL <u>CT-1P</u>		
SERIAL NO. <u>2632794</u>		
TYPE OF JOB ☒ REPAIR ☐ MODIFICATION ☐ MAINTENANCE ☐ CHARGEABLE ☐ WARRANTY ☐ CONTRACT NO. _____ ☐ INSTALLATION ☐ ORDER NO. _____ ☐ INVOICE NO. _____		
COMPLAINT <u>* Chinrest (up/down) movement not working.</u>		
ACTION <u>- I have checked all connections of the chinrest</u> <u>- I have tied the (up/down) motor cable good with the chinrest PCB.</u> <u>- Now, All movements are working good.</u>		
TOTAL HOURS	WORK	TRAVEL
		JOB COMPLETED ☒ YES ☐ NO
PARTS USED		
ITEM	PART NO	DESCRIPTION
CUSTOMER NAME <u>KE MARCELINE</u>	HOSP. ENGR. NAME	ENGINEER NAME <u>Ahmed</u>
SIGNATURE <u>29/12/24</u>	SIGNATURE	SIGNATURE <u>[Signature]</u>