



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 26/3/24Requested by Swathy prasadDepartment Ward Location 5A

SR. No.	Machine	Model	Complaint
<u>P 770 B1404</u> <u>0004</u>	<u>DVT machine</u>	<u>DVT</u> <u>7700</u>	<u>cuff is not</u> <u>working</u>

Check within Week ASAP

Engineer Comments

Cancel working

End Comments

Requested by 

Checked By _____

Approved by _____

ATCO Technology Co.

Tel: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهرام , ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 59254

Customer	Aloof Hospital	Equipment	compressable limb therapy system
		Model No.	DVT - 7700
		Serial No.	P770B1H0H000H
Authorized Person		Manufacturer	Wonjin Mulsan.
Customer Complaint		Location	ward 5A
	Cuff not working.	Contract / Order No.	

Services / Check Carried out

- | | |
|---|---|
| ☐ Inspection / Cleaning | ☐ Optics Checks |
| ☐ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☐ Safety Checks | ☐ Operational Error |
| ☐ Electrical / Electronics | ☐ Mechanical Checks |
| ☐ Accessories Check | ☐ _____ |

- | | |
|---|---------------------------------|
| ☐ Installation | ☐ Warranty |
| ☒ Repair | ☐ On Charge |
| ☐ Maintenance | ☐ Contract |
| ☐ Upgrade | ☐ _____ |

Time Spent

Remarks

Service call attended.
we inspect the unit and checked the cuff.
we connect the limb and tried to pressuring. the
cuff is pressuring.
Currently the unit is working properly. we couldn't
found any error on the cuff.

No.	Spare Parts Used	Part No.	Qty.

Service Engineer Niscom ATCO Technology Co. Signature Date 26/03/2024	Authorized Person Signature Date	Customer / User Signature Date
---	--	--