

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهر، ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 61016

Customer	Aflok Hospital Jahra	Equipment	Endoscopy Machine & Monitor
		Model No.	Sen 3
		Serial No.	25786
Authorized Person		Manufacturer	Soluscope
Customer Complaint	Error 12 Error 13	Location	(2nd Flr.) Endoscopy Unit
		Contract / Order No.	

- | | |
|---|--|
| ☐ Installation | ☐ Warranty |
| ☒ Repair | ☒ On Charge |
| ☐ Maintenance | ☐ Contract |
| ☐ Upgrade | ☐ _____ |

Time Spent

Services / Check Carried out

- | | |
|---|---|
| ☐ Inspection / Cleaning | ☐ Optics Checks |
| ☐ Calibration / Performance | ☐ Pneumatic Checks |
| ☐ Interface / Communication | ☐ Hydraulic Checks |
| ☐ Safety Checks | ☐ Operational Error |
| ☐ Electrical / Electronics | ☐ Mechanical Checks |
| ☐ Accessories Check | ☐ _____ |

Remarks

Service call attended. Checked and found
tubings for SOL A & SOL B damaged and
defective SOL A pump. Replaced the items.
Solved the leakage on clamping chamber.
Replaced all NPV's. Done cycle 6 and
completed. Checked and found that
the unit is working properly. Cycle count - 1308

No.	Spare Parts Used	Part No.	Qty.
①	SOL0213 - ①	⑥ SOL0171 - ②	⑪ SOL0135 - ①
②	SOL0130 - Tubings - 2nos	⑦ SOL0044 - ②	⑫ SOL0046 - ①
③	SOL0127 - Tubing - 2nos	⑧ SOL0061 - ①	⑬ SOL0047 - ①
④	SOL0136 - ①	⑨ SOL0043 - ①	
⑤	SOL0149 - ①	⑩ SOL0212 - ①	

Service Engineer

ATCO Technology Co.

Signature

Date

Authorized Person

Signature

Date

Customer / User

Signature

Date

شاهان سلمان غنيم
مستشار طبي
22020120379

19/10/2024