

Mr. Tawk



MEDICAL EQUIPMENT REPAIR REQUEST

No. 6454842

Date: 10/2/24

Requested by DRASEM KAMAL

Department DENTAL Location AL'ORF

SR. No.	Machine	Model	Complaint
<u>4336</u>	<u>SIRONA</u>	<u>D3613</u>	<u>The machine is not dispensing water during scaling procedure</u>

Check within

☐ Week

☒ ASAP

Engineer Comments

Need to replace new sensor

End Comments

Replaced new sensor in scaling

D. Asem Kamal

Requested by

Checked By

Approved by

د. عاصم محمد كامل
اختصاصي علاج اللثة
مستشفى العرف

فاتورة نقدأ
Cash Invoice

التاريخ 13/2/2024 Date

Mr./Messrs

Alarf Hospital

المباع للسيد / للسادة

Address

تاريخه

طلب شراء رقم

العنوان

البيان Description	الشدة Pack.	الوحدة Unit	الكمية Qty.	سعر الوحدة Unit Price		القيمة الاجمالية Total Price	
				دينار K.D.	فلس Fils	دينار K.D.	فلس Fils
Dr. Asem							
Scaler Sensor board Sensor replaced			1	60	-	60	-
د. هاشم محمد كامل مستشفى السورف د. هاشم محمد كامل							
Total K.D.				Sixty KD		60	-

E.&O.E. ماعدا السهو والخطأ

البضاعة المباعة لا ترد ولا تستبدل
استلمت البضاعة بحالة جيدة واتعهد بتسديد القيمة حين الطالب.

توقيع المستلم

اسم المستلم

البائع