

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO. 336218



log no - 2076

شركة أتكو التكنولوجية

تلفون: (+965) 24743017 / 24567725

فاكس: (+965) 24743019 / 24567792

ص.ب: 2355 الجاهراء، 01025 - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. 336218

SERVICE / INSTALLATION REPORT

No.: 58308

Customer	Aloft Hospital			Equipment	Incubator		
				Model No.	C60		
				Serial No.	14093 - 0322		
Authorized Person				Manufacturer	Labotect		
Customer Complaint				Location	IVF lab.		
CO2 sensor Defect: Alarm				Contract / Order No.			
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐				☐ Installation		☐ Warranty	
				☒ Repair		☐ On Charge	
				☐ Maintenance		☐ Contract	
				☐ Upgrade		☐	
				Time Spent			
Remarks Service call attended, while we inspect the unit the unit shows alarm CO2 sensor Defect. It seems that the CO2 sensor is faulty. Need to replace the CO2 sensor. Quote will be given.							
No.	Spare Parts Used			Part No.		Qty.	
Service Engineer Miran/Sujith ATCO Technology Co. Signature Date 20/01/2024.		Authorized Person MIRA / 20-1-24 Signature Date		Customer / User Signature Date			