



قسم الصيانة
SERVICE REPORT

8112

Customer : Albani Hospital

Date: 17/09/2024

Department: NIICU

Type of equipment : EROScan Monaco

Model No.: EROScan

Serial No.: 8106837

Service Call Type :

installation

Repair

Maintenance

Emergency

☐☒☐☐

Warranty

Contract

Chargeable

Others

☐☐☐☐

ENGINEER'S REPORT :

Fault : Testing probe issue

Action : Testing probe needs to be replaced

Remarks :

Warranty :

Repair Time :

Parts Used :

Invoice No.:

Date :

K.D.

Fils

ENGINEER'S NAME AND SIGNATURE

CUSTOMER'S NAME AND SIGNATURE