

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 5/11/24

Requested by _____

Department ER Location Male, pedu, female observation

SR. No.	Machine	Model	Complaint
1	pedu Bed no-3		sicle rail not working
2	Male 1 Bed		Break not working. p. of
3	Female Bed no-2		Remote not working while elevating

Check within Week

ASAP

Engineer Comments

End Comments

Bamul

Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهره , ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63452

Customer	Alor Hospital		Equipment	Patient bed.	
			Model No.	LA 6018 MAPL	
			Serial No.	058466	
Authorized Person			Manufacturer	Corona	
Customer Complaint	Height adjuster not working		Location	4th floor (ER)	
Services / Check Carried out			Contract / Order No.		
			Time Spent		
☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐			☐ Installation ☒ Repair ☐ Maintenance ☐ Upgrade		
			☐ Warranty ☐ On Charge ☐ Contract ☐		
Remarks					
Service call attended, we inspect the unit and found that the height adjustment not working we repaired the control unit and fixed the unit. Now the unit is working properly.					
No.	Spare Parts Used		Part No.	Qty.	
Service Engineer		Authorized Person		Customer / User	
Nizam ATCO Technology Co.		[Signature]			
Signature		Signature		Signature	
Date		Date		Date	
06/11/2014					

Customer <u>Aloof Hospital</u>	Equipment <u>Emergency trolley bed</u>		
	Model No.		
	Serial No. <u>NA</u>		
Authorized Person	Manufacturer		
Customer Complaint	Location <u>ER</u>		
<u>one side height adjustment</u> <u>lever not working.</u>	Contract / Order No.		
	☐ Installation ☐ Warranty ☒ Repair ☐ On Charge ☐ Maintenance ☐ Contract ☐ Upgrade ☐ _____		
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐ _____	Time Spent		
Remarks <u>Service call attended</u> <u>we inspect the unit and found that the</u> <u>height pedal connection with the hydraulic jack</u> <u>is miss aligned. we repaired and fixed</u> <u>it properly.</u> <u>checked and confirmed that the unit is</u> <u>working properly.</u>			
No.	Spare Parts Used	Part No.	Qty.
Service Engineer <u>NIXON</u> ATCO Technology Co. Signature: <u>[Signature]</u> Date: <u>06/11/2024</u>		Authorized Person <u>[Signature]</u> <u>7/11/2024</u> Signature: _____ Date: _____	
		Customer / User Signature: _____ Date: _____	