

Customer <u>Al orb Hospital</u>		Equipment <u>Suction-Imigation</u>	
		Model No. <u>2P-1000</u>	
		Serial No. <u>E03CNA0 00008</u>	
Authorized Person		Manufacturer <u>Zerone</u>	
Customer Complaint		Location <u>OT</u>	
<u>Fixing side plate</u>		Contract / Order No.	
Services / Check Carried out ☐ Inspection / Cleaning ☐ Optics Checks ☐ Calibration / Performance ☐ Pneumatic Checks ☐ Interface / Communication ☐ Hydraulic Checks ☐ Safety Checks ☐ Operational Error ☐ Electrical / Electronics ☐ Mechanical Checks ☐ Accessories Check ☐ _____		☐ Installation ☐ Warranty	
		☒ Repair ☐ On Charge	
		☐ Maintenance ☐ Contract	
		☐ Upgrade ☐ _____	
		Time Spent	
Remarks <u>service call attended.</u> <u>As a customer request, we fixed the side plate and which</u> <u>giving from the customer, we connected the other side in the table.</u> <u>we checked all the connections are clear and not damage.</u> <u>we checked the table unit and it's fixed as the customer needs.</u>			
No.	Spare Parts Used	Part No.	Qty.
	<u>fixed and</u> <u>installed</u>		
Service Engineer <u>Nixon f Mousa</u> ATCO Technology Co. Signature <u>[Signature]</u> Date <u>28-08-2024</u>		Authorized Person <u>[Signature]</u> <u>29/8/24</u> Signature Date	
		Customer / User Signature Date	