

MEDICAL DENTAL LAB

Service Report No. 4822

[illegible]

D	M	Y
20	5	25
Item Code		
Contract No.		
Warranty	☐	
Contract	☐	
Repair	☐	
Installation	☐	
Maintenance	☒	
Time		
On Site	Waiting	Travelling
Engineer		
M. Zahra		

Action Taken

* machine is working fine. but there is a small note that I would like to share:- The inlet of the valve module is Broken, Now there is no problem. but it might cause an issue in future.

Job Completed ☒ Yes ☐ No **Waiting for parts** ☐ Yes ☐ No

Cura Engineer Signature

A handwritten signature in blue ink, consisting of a stylized 'C' followed by a large loop and a diagonal stroke.

User Signature & Stamp

Any one
26/05/2025

Biomedical Signature & Stamp