

P.O.Box : 24240 Safat
Code : 13103 | Kuwait
C.R Number : 353520
Capital 500,000 K.D



ص.ب : 24240 الصفاة
الرمز : 13103 | الكويت
السجل التجاري : 353520
رأس المال 500,000 د.ك

SERVICE REPORT

NO. 1066

SERVICE CALL NO.

Customer's name & address <u>Al Ory Hospital</u>				Equipment <u>MRI Injector</u>			
Contact person				Serial No. <u>311801880011842</u>			
Department <u>Radiology</u>				Model No. <u>Magnetom Espree / Avation MR</u>			
Tel. No.				Manufacturer <u>Siemens / Medtron</u>			
Maint. Cont.				Ord. No.			
Inv. No.				Date <u>23/06/2025</u>			
INSTALLATION ☐ WARRANTY ☐ PREVENTIVE MAINTENANCE ☐ CHARGEABLE ☐ REPAIR ☒ UPGRADE ☐ UPDATE ☐							
<u>Description of WORK DONE :</u> <u>* CM side was Not detecting 200ml syringe</u> <u>* the sensors was covered with contrast after</u> <u>cleaning the Problem solved</u> <u>* Machine is working and give to the customer in a working condition</u>							
Repair Completed Yes ☒ No ☐							REMARKS
Eng	Date	Time		HRS.		Over Hrs.	
		From	To	Work	Wait	Trav.	
<u>OJ</u>	<u>23/06/2025</u>						
SPARE PARTS USED:							
Description		Article No.		Stock No.		Qty.	
Parts to be Ordered :		Article No.		Description:		Qty:	
Service Engineer's name & Signature <u>Omar Jarad</u>				CUSTOMER's name & signature <u>[Signature]</u>		APPROVED BY:	
Date <u>23/06/2025</u>				Date		Date	



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 24/6/25

Requested by _____

Department _____ Location Radiology

SR. No.	Machine	Model	Complaint
	pressure injector mer		contrast media injector not working.

Check within

Week

ASAP

Engineer Comments

End Comments

Qithana.K.Reje

Requested by

Checked By

Approved by