



FIELD SERVICE REPORT

DEPT: Lab 24/ 11315

CUSTOMER <u>Private</u>		EQUIPMENT <u>Hematology - Sysmex</u>		MODEL NO. <u>XN-330</u>		DATE <u>10 / 4 / 2025</u>	
JOB NO.		LOCATION <u>ALORF hospital</u>		SERIAL NO. <u>17866</u>		ASSET	
PARTS USED						CONTRACT	
						COST CENTER	
						BILL PARTS / LABOR ☐	
						WARRANTY ☐	
						CONTRACT ☒	
						INSTALLATION ☐	
						OTHERS ☐	
						ENGINEER <u>Easa</u> HOURS <u>-</u>	

PROBLEM, DIAGNOSIS AND ACTION

- * Preventive Maintenance (PMs)
- * Checked and Cleaned the Instrument and Internal parts
- * Flush Reaction Chambers with CellClean Manually.
- * Drained Reaction chambers and waste fluid chamber.
- * Cleaned Transducer by brush and RBC clogs Removed.
- * Perform Rinse Flowcell and Air Bubbles Removal.
- * Cleaned filter and checked FCM syringe, Tubes and Sensors.
- * Run QC passed and checked.

REMARKS

* PM Done.

JOB COMPLETED



Yes



No

AWAITING PARTS



Yes



No

ATC ENGINEER SIGNATURE

Easa
Easa Diab.

USER SIGNATURE

Harry WZ Hanna
د. هاني وليد زكي حنا
طبيب مسجل اول بيوكيمستري
مستشفى العرف
22025120371

AUTHORIZED SIGNATURE & STAMP

 مستشفى العرف
ALORF HOSPITAL

www.atc.com.kw