

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 30/09/2014

Requested by Dr. Ivan S/GRV

Department OPD - ENT Location 2nd floor

SR. No.	Machine	Model	Complaint
11163025	Entemed (ENT Unit)	Futurent 111	leaking from the ear irrigation nozzle and difficulty in removing the ear wax tip or cannula from the nozzle or connector.

Check within Week

☒ ASAP

Engineer Comments

tighten the handpiece there in ear irrigation

End Comments

Unit is working properly.

Dr. Ivan S/GRV

Requested by

Checked By

Approved by

ATCO Technology Co.

Tel: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



1143
شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهرام , ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 59255

Customer	Alorx Hospital.		
Equipment	ENT workstation		
Model No.	Futurent 111		
Serial No.	111632025		
Authorized Person	Manufacturer		
Customer Complaint	Location		
	Contract / Order No.		
Services / Check Carried out	☐ Installation ☐ Warranty		
☐ Inspection / Cleaning	☐ Optics Checks	☒ Repair	☐ On Charge
☐ Calibration / Performance	☐ Pneumatic Checks	☐ Maintenance	☐ Contract
☐ Interface / Communication	☐ Hydraulic Checks	☐ Upgrade	☐
☐ Safety Checks	☐ Operational Error	Time Spent	
☐ Electrical / Electronics	☐ Mechanical Checks		
☐ Accessories Check	☐		
Remarks	Service call attended. Entenna Irrigation tip. loosened from the threaded hand piece. we tighten the handpiece threads checked and Confirmed That there is no leakage. Unit is working properly.		
No.	Spare Parts Used	Part No.	Qty.
Service Engineer	Authorized Person	Customer / User	
Nixon			
ATCO Technology Co.			
Signature	Signature	Signature	
Date	Date	Date	
31/03/2024	14/3/24		