

MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 12-06-25

Requested by ROWENA ERIKA CABILES

Department ENT Location 5th Floor OLD BLDG.

SR. No.	Machine	Model	Complaint
111632045	ENT work station	Enturent III	water leaking from handpiece

Check within

☐ Week

☒ ASAP

Engineer Comments

End Comments


ROWENA ERIKA CABILES

Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو التكنولوجيه

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجهراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63773

Customer	Alst Hospital Jahra		Equipment	ENI Workstation	
			Model No.	FUTURENT 111	
			Serial No.	11163 2045	
Authorized Person			Manufacturer	EXTOR MED	
Customer Complaint	Water leaking from hand piece		Location	5th Floor	
			Contract / Order No.		
Services / Check Carried out	☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check		☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐	☐ Installation ☒ Repair ☐ Maintenance ☐ Upgrade	☐ Warranty ☐ On Charge ☐ Contract ☐
			Time Spent		
Remarks	Service call attended. Checked the unit and solved the problem for water leaking from the handpiece. Checked and found that the unit is working properly. Unit is under observation.				
No.	Spare Parts Used	Part No.	Qty.		
	still leaking				
Service Engineer	Authorized Person	Customer / User			
Signature	Signature	Signature			
Date	Date	Date			
12/06/2025					