



MEDICAL EQUIPMENT REPAIR REQUEST

No. _____

Date: 19/12/24

Requested by Jemymol Varghese

Department LDR Location Room 2

SR. No.	Machine	Model	Complaint
<u>SN 27192</u>	<u>light centric</u>	<u>Penta 28</u>	<u>Not working</u>

Check within Week

ASAP

Engineer Comments

End Comments

[Signature]
Requested by

Checked By

Approved by

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO : 336218



شركة أتكو التكنولوجية

تلفون : ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس : ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب : ٢٣٥٥ الجھراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63784

Customer	Alor Hospital			Equipment	OBSERVATION LIGHT		
				Model No.	PENTA 28		
				Serial No.	27192		
Authorized Person				Manufacturer	RIMSA		
Customer Complaint				Location	LDR		
No. Power.				Contract / Order No.			
Services / Check Carried out ☐ Inspection / Cleaning ☐ Calibration / Performance ☐ Interface / Communication ☐ Safety Checks ☐ Electrical / Electronics ☐ Accessories Check ☐ Optics Checks ☐ Pneumatic Checks ☐ Hydraulic Checks ☐ Operational Error ☐ Mechanical Checks ☐				☐ Installation		☐ Warranty	
				☒ Repair		☐ On Charge	
				☐ Maintenance		☐ Contract	
				☐ Upgrade		☐	
				Time Spent			
Remarks Service call attended. we inspect the unit and found that the cable inside the power plug broken. we replaced the 3pin power plug with new one. checked and confirmed that the unit is working properly.							
No.	Spare Parts Used			Part No.		Qty.	
1	3 pin plug					1	
Service Engineer WISCON ATCO Technology Co. Signature Date 22/12/2024.		Authorized Person Signature Date		Customer / User Signature Date 30-12-24			