



MEDICAL EQUIPMENT REPAIR REQUEST

No. 1

Date: 12/11/24

Requested by Andre Dubouzet

Department OR Location OR

SR. No.	Machine	Model	Complaint
2007/2001935	Defibrillator	700	no battery power

Check within

☐ Week



☒ ASAP

Engineer Comments

End Comments

Requested by

Andre

Checked By

KCMARCEUND

Approved by

12/11/24

ATCO Technology Co.

Tel.: (+965) 24743017 / 24567725

Fax: (+965) 24743019 / 24567792

P.O. Box: 2355 Jahra, 01025 - Kuwait

Email: sales@atco-kuwait.com

www.atco-kuwait.com

CR NO . 336218



شركة أتكو للتكنولوجيا

تلفون: ٢٤٧٤٣٠١٧ / ٢٤٥٦٧٧٢٥ (+٩٦٥)

فاكس: ٢٤٧٤٣٠١٩ / ٢٤٥٦٧٧٩٢ (+٩٦٥)

ص.ب: ٢٣٥٥ الجھراء, ٠١٠٢٥ - الكويت

Email: sales@atco-kuwait.com

www.atco-kuwait.com

س.ت. ٣٣٦٢١٨

SERVICE / INSTALLATION REPORT

No.: 63522

Customer	Alex Hospital Jahra	Equipment	Defibrillator
		Model No.	Reanibex 700
		Serial No.	200720021935
Authorized Person		Manufacturer	Bexen
Customer Complaint		Location	OK
		Contract / Order No.	
Services / Check Carried out	☐ Installation ☐ Warranty ☐ Repair ☐ On Charge ☐ Maintenance ☐ Contract ☐ Upgrade ☐		
☐ Inspection / Cleaning ☐ Optics Checks ☐ Calibration / Performance ☐ Pneumatic Checks ☐ Interface / Communication ☐ Hydraulic Checks ☐ Safety Checks ☐ Operational Error ☐ Electrical / Electronics ☐ Mechanical Checks ☐ Accessories Check ☐	Time Spent		
Remarks	As per request, checked the shock tests with analyser and it's working properly. Performed hardware, boot panel and paddle interfaces tests. Checked the unit is without battery. Checked and found it's working properly.		
No.	Spare Parts Used	Part No.	Qty.
①	SDJ - Measured value - 119.5J		
②	100J - Measured value - 93.6J		
③	200J - Measured value - 200.2J		
NOTE: BATTERY PACK - up NOT WORKING			
Service Engineer	Authorized Person	Customer / User	
Signature Date 27/11/2024	Signature Date 2/1/25	Signature Date	